


**CORNER RECORD**Document Number CR 1285City of BERLEYCounty of ALAMEDA, CaliforniaBrief Legal Description LOT 11, BLOCK 9, CRAGMONT (BOOK 23, PAGE 15)**CORNER TYPE**

Government Corner ☐ Control ☐  
 Meander ☐ Property ☐  
 Rancho ☐ Other ☐  
 Date of Survey APRIL 20, 1999

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29 ☐ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☐

Corner -- Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

-STANDARD CITY MONUMENTS FOUND AS SHOWN ON PAGE 2 (SHOWN ON MONUMENT MAP OF CRAGMONT TRACT ON FILE WITH THE CITY OF BERKLEY SURVEYORS OFFICE).

A description of the physical condition of the monument as found and as set or reset:

-SET BRASS TAG STAMPED "L.S. 6914" @ MOST SOUTHERLY CORNER OF LOT 11, BLOCK 9  
-SET 5/8" REBAR WITH YELLOW PLASTIC CAP STAMPED "L.S. 6914" AT ALL OTHER CORNERS

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 2, 1999

Signed Bruce Storrs P.L.S. or R.C.E. No. L.S. 6914

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 12-08-1999

and examined and filed 1-26-2000

Signed Deid Penland P.L.S. or R.C.E. No. 5726

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

